

Installation instructions For set # 3.1109

1982-92 Camaro-Firebird Secondary crossmember mounts



Important:

Before reassembling x-member. Check for cracks at main transmount mounting area. IF cracked, it mst be replaced or repaired. Recommended for use with polyurethane main transmission mount. Part #3-1108



Installation instructions

For set # 3.1109 1982-92 Camaro-Firebird Secondary crossmember mounts



1131 VIA CALLEJON, SAN CLEMENTE, CA 92673

C 2007 Energy Suspension. All rights reserved. May not be reproduced, in any form, or by any means, without the written consent of Energy Suspension.

Important:

17107 5/MAR/07 BRH Before reassembling x-member. Check for cracks at main transmount mounting area. IF cracked, it mst be replaced or repaired. Recommended for use with polyurethane main transmission mount. Part #3-1108

